WAX RECOMMENDATION

Bogus New Year's Skate

Bogus Basin, Boise, ID
Saturday, January 1
3 P.M.
1K/5K/15K, Skate
Mass start
1-3 laps
https://www.bbnt.ski/race

Forecast/Conditions: Significant snowfall and cold temperatures throughout week. Friday night low of -2F, Saturday high of 13. Start temperature of 12 and 75 percent humidity.

Glidewax: Apply High Performance Blue Hot Wax, scrape and brush. Spray High Performance Blue Liquid Paraffin on to the polishing side of a Thermo Cork and wipe over the glide zone, let stand overnight, then polish with the Polishing Brush Liquid Paraffin. If you do not have LP spray substitute BP Blue Hot Wax for the HP Blue Hot Wax base, then apply HP Blue Hot Wax, scrape and brush.

Structure: A fine or universal structure covered by one pass with the Blue Structurite tool after scraping and brushing HP Hot Wax or before applying HP LP will best suit these conditions.

Racing - Service

Created by Randy Anderson, Toko Tech Team member since 2015, Highbasin@gmail.com

Check the Wax Tips page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.