

WAX RECOMMENDATION



Kongsberger Stampede

Cabin Creek Exit 63 Hwy 90, Snoqualmie Pass, WA

Sunday, February 4

10 A.M.

15K/5K, Freestyle technique

Wave starts

15K is 3 laps

<http://www.kongsbergers.org>

Forecast/Conditions: Overnight low of 39 Saturday night with rain falling before and during event. Daytime high of 43 Sunday. Deep snowpack of near 40 inches. Expect soft and slow conditions.

Glidewax: Apply LF Black, scrape and brush, then apply HF Yellow, scrape and brush. Finish by crayoning JetStream Yellow, iron hot (320F) with a layer of fiberlene under the iron, traveling slowly (60 seconds) tip to tail. Brush with a dedicated nylon polishing brush and polish with a thermopad. For fastest skis, finish by spraying HelX 2.0 Yellow, let dry, go ski. Do not brush.

Gripwax: NA

Structure: A universal or warm structure covered by one pass with the Yellow Structurite tool followed by an application of HelX 2.0 Yellow will best suit these conditions.

Created by David Ford, Toko Tech Team member since 2003. Dave@TokoUS.com

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the Fluorocarbon (JetStream or HelX) and substitute the LF or NF wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.

Racing - Service