

WAX RECOMMENDATION



Pinedale Stampede

White Pine Resort, Pinedale, WY

Saturday, February 27

10 A.M.

6.5K/13K/20K, Skate technique

Mass start

Multiple loops

<https://www.pinedaleaquatic.com/stampede>

Forecast/Conditions: Overnight low in the single digits, temperature at start in the low teens. Fresh snow, overcast skies.

Glidewax: Apply Base Performance Blue Hot Wax, scrape and brush. Spray on Base Performance Liquid Paraffin Blue, let stand overnight, then polish with the Polishing Brush Liquid Paraffin. If you do not have Liquid Paraffin, after scraping and brushing the BP Blue Hot Wax, apply an additional layer of BP Blue Hot Wax, scrape and brush.

Structure: A fine structure covered by one pass with the Blue Structurite tool after scraping and brushing the final BP Hot Wax or before spraying BP Liquid will best suit these conditions.

Racing - Service

Created by Erich Wilbrecht, Toko Tech Team member. erich.wilbrecht@jhsir.com

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If an event allows fluorinated waxes and you choose to use them, use High Performance or Performance (Liquid Paraffin or Hot Wax) of the same color (Yellow, Red or Blue), as the temperature ranges are the same. To see optimal application procedures for both Glidewax and Gripwax, go to the [How To](#) link at TokoUS.com.