



Kongsbergers Ozbaldy

Cabin Creek Exit 63 Hwy 90, Snoqualmie Pass, WA Sunday, March 3 9 A.M. First Wave Start 50K, 10K, 5K, Skate 10K loop

http://www.kongsbergers.org

Forecast/Conditions: Overnight low of 22 rising to about 24 snow temperature at the start with clean, firm and medium fast conditions that will break down a bit with the multiple laps. For once, it is predicted to be untransformed snow! A 60 percent chance of snow showers during event and a daytime high of around 32.

Glidewax: Apply High Performance Red Hot Wax/HP Yellow Hot Wax mixed 1:1, scrape and brush. Then spray on High Performance Yellow Liquid Paraffin, let stand overnight, then polish with the Polishing Brush Liquid Paraffin. If you do not have LP spray, apply BP Red Hot Wax, scrape and brush, then apply HP Yellow Hot Wax, scrape and brush.

Gripwax: N/A

Structure: A universal structure covered with one pass with the Yellow Structurite tool after scraping and brushing the final Hot Wax

or before spraying HP LP will best suit these conditions. Created by David Ford, Toko Tech Team member since 2003. fordstruc@gmail.com Check the Wax Tips page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.

ervic