

WAX RECOMMENDATION



Great Nordeen

Mt. Bachelor, Bend, OR

Sunday, January 29

7:30 A.M.

30K/18K, Skate

Mass start

Point to point

www.mbsef.org

Forecast/Conditions: Overnight low of 22, partly cloudy. High of 38 on Sunday, partly cloudy.

Glidewax: Apply LF Black, scrape and brush, then apply HF Red, scrape and brush. Finish by crayoning JetStream Red, iron hot (320F) with a layer of fiberlene under the iron, traveling slowly (60 seconds) tip to tail. Brush with a dedicated nylon polishing brush and polish with a thermopad.

Gripwax: N/A

Structure: A medium linear structure covered by one pass with the Red Structurite tool (before JetStream application) will best suit these conditions.

Created by Colin Mahood, Toko Tech Team member since 2000.

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the Fluorocarbon (JetStream) and substitute the LF or NF wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.

Racing - Service