

WAX RECOMMENDATION



Lapham Loppet

Lapham Peak, Delafield, WI

Saturday, January 19

10:30 A.M.

11K Freestyle

Multiple laps on an artificial snow loop

www.laphampeaksnowmaking.org/activities/lapham-loppet/

Forecast/Conditions: Friday night snow. Low around 17 and 80 percent chance of precipitation with some snow accumulation likely. Saturday snow likely, mainly before noon. Mostly cloudy, with race temperature of 20. Chance of precipitation is 60 percent. New snow accumulation of less than one inch possible. Expect a mix of artificial and fresh snow packed and machine worked together.

Glidewax: Apply LF Blue, scrape and brush, then apply HF Blue, scrape and brush. Finish by crayoning JetStream Red due to the aggressive snow, iron hot (320F) with a layer of fiberlene under the iron, traveling slowly (60 seconds) tip to tail. Brush with a dedicated nylon polishing brush and polish with a thermopad.

Structure: A universal grind covered by one pass with the Blue Structurite tool before JetStream application will best suit these conditions.

Racing - Service

Created by Ben Lund, Toko Tech Team member since 2003.

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the Fluorocarbon (JetStream or HelX) and substitute the LF or NF wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.