

WAX RECOMMENDATION

TOKO[®]

Stowe Derby

Stowe, VT

Sunday January 13

10 A.M. Skate start, noon Classic start

20K, Point-to-Point, finish at Trapps

Interval start, 5 skiers every 30 seconds

<https://mmsc-mmwa.org/events/stowe-derby/>

Forecast/Conditions: Saturday cloudy, overnight low about -4F. Sunday partly cloudy. The snow temperature at skate and classic race time will be about 5F on the trails lower on the mountain. There will be a 10 to 15 minute climb to the Trapps trails. Pistenbully groomed packed powder.

Glidewax: Apply LF Blue, scrape and brush, then apply HF Blue, sprinkle on X-cold Powder, iron in together, scrape and brush. Finish by crayoning JetStream Blue, iron hot (320F) with a layer of fiberlene under the iron, traveling slowly (60 seconds) tip to tail. Brush with a dedicated nylon polishing brush and polish with a thermopad.

Gripwax: Roughen base with 150 grit sandpaper, iron in Nordic Base Wax Green, cork smooth, let cool. Then apply 4 layers of Nordic GripWax X-Cold, corking between layers.

Structure: A fine structure covered by one pass with the Blue Structurite tool (before JetStream application) will best suit these conditions.

Created by Dave Boucher, Toko Tech Team member since 1999.

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the Fluorocarbon (JetStream or HelX) and substitute the LF or NF wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.

Racing - Service