

WAX RECOMMENDATION



Owl Creek Chase

Snowmass XC Center, Snowmass, CO

Sunday, February 9

9 A.M.

21K Skate/Classic

Mass start

Point-to-Point, Snowmass to Aspen Nordic Center

More info [here](#)

Forecast/Conditions: Saturday night low of 16 warming to mid-20s by race start. Snow is likely during the race.

Glidewax: Apply Performance Black Hot Wax, scrape and brush, then apply High Performance Blue Hot Wax, scrape and brush. For HP Liquid Paraffin, apply Performance Blue Hot Wax, scrape and brush, then spray on HP Liquid Blue, let sit in a warm room for at least one hour (overnight is best), polish with the Polishing Brush Liquid Paraffin.

Gripwax: Roughen base with 150 grit sandpaper, iron in Nordic Base Wax Green, cork smooth, let cool. Then apply 3-4 alternating layers of Nordic GripWax Red/Blue, corking between layers. Finish with Blue.

Structure: A fine structure covered by one pass with the Blue Structurite tool after scraping and brushing HP Hot Wax or before spraying Liquid Paraffin will best suit these conditions.

Racing - Service

Created by Stephen White, Toko Tech Team member since 2005. xcwhite@TokoUS.com

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the High Performance (Liquid Paraffin or Hot Wax) and substitute the Performance or Base Performance wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the [How To](#) link at TokoUS.com.