

WAX RECOMMENDATION



Solitude Nordic Spring Fling

Solitude Nordic Skiing Center, Brighton, UT

Saturday, March 14

10 A.M. 7.5K, Freestyle technique

1 P.M. Relay race

3 laps on a 2.5K loop

www.utahnordic.com/events/2020/solitude-nordic-spring-fling

Forecast/Conditions: Overnight low 26, temperature at start about 30 with chance of snow. The snow is partially transformed and not "corn snow."

Glidewax: Apply Performance Black Hot Wax, scrape and brush, then apply High Performance Red Hot Wax, scrape and brush. For HP Liquid Paraffin, apply Performance Blue Hot Wax, scrape and brush, then spray on HP Liquid Red, let sit in a warm room for at least one hour (overnight is best), polish with the Polishing Brush for Liquid Paraffin.

Gripwax: NA

Structure: A universal stone grind structure covered by one pass with the Red Structurite tool followed by one pass with the Blue Structurite tool after scraping and brushing HP Hot Wax or before spraying HP LP will best suit these conditions.

Created by Barry Makarewicz, Toko Tech Team member since 2000.

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. The Toko Race Wax Tips offer racers precise waxing advice on how to make your skis perform optimally for a given event. For racers who don't have top end waxes, skip the High Performance (Liquid Paraffin or Hot Wax) and substitute the Performance or Base Performance wax of the same color (Yellow, Red or Blue). To see optimal application procedures for both Glidewax and Gripwax, go to the [How To](#) link at TokoUS.com.

Racing - Service