

WAX RECOMMENDATION



Alley Loop

Crested Butte, CO

Saturday, February 6

Rolling starts from 7 A.M to 8 A.M. and 11 A.M. to Noon

21K & 42K, Skate & Classic

loops

More info [Here](#)

Forecast/Conditions: Overnight low of 4F, morning start in the single digits F, later start in the upper teens. New snow forecasted for Wednesday through late Friday. Saturday should provide mostly sunny skies. Early starters should consider a couple of layers of BP Blue to harden the bases for cold snow and the most likely dirty snow present in town.

Glidewax: Apply Base Performance Blue Hot Wax, scrape and brush. Spray on Base Performance Blue Liquid Paraffin, let stand overnight, then polish with the Polishing Brush Liquid Paraffin. If you do not have LP spray, after scraping and brushing BP Blue Hot Wax, apply another layer of BP Blue Hot Wax, scrape and brush.

Gripwax: Roughen base with 150 grit sandpaper, iron in Nordic Base Wax Green, cork smooth, let cool. Then apply 5-6 thin layers of Nordic GripWax Blue, (Red for later starters), corking between layers.

Structure: A fine structure covered by one pass with the Blue Structurite tool after scraping and brushing the final BP Hot Wax or before spraying BP Liquid will best suit these conditions.

Created by Stephen White, Toko Tech Team member since 2005. xcwhite@TokoUS.com

Check the [Wax Tips](#) page at [TokoUS.com](#) before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If an event allows fluorinated waxes and you choose to use them, use High Performance or Performance (Liquid Paraffin or Hot Wax) of the same color (Yellow, Red or Blue), as the temperature ranges are the same. To see optimal application procedures for both Glidewax and Gripwax, go to the [How To](#) link at [TokoUS.com](#).

Racing - Service