

SMR Stampede Skate

Snow Mountain Ranch, Granby, CO Saturday, March 11 9 A.M. 50K, 25K, 12.5K, 3K, Skate Mass start by distance 12.5K loop More info here

Forecast/Conditions: Snow and high winds likely Friday through race start with an overnight low in the mid-20s warming to above freezing by race start. Track conditions will be soft. The wind will help keep the snow on the cold side.

Glidewax: Apply Base Performance Blue Hot Wax, scrape and brush. Then apply High Performance Red Hot Wax, scrape and brush.

Gripwax: N/A

Structure: A fine structure covered by one pass with the Red Structurite tool after scraping and brushing the final Hot Wax will best suit these conditions.

Service

Created by Stephen White, Toko Tech Team member since 2005, xcwhite@gmail.com

Check the Wax Tips page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.