## WAX RECOMMENDATION TOKO



## 2024 Tour de Stowe

Trapps Outdoor Center, Stowe, VT Saturday, January 20 11 A.M. 25K/15/5K. Classic

https://www.skireg.com/tour-de-stowe

Forecast/Conditions: Overnight low of 3F with the temperature rising to 6F by start time. Cloudy conditions with light wind. Snow will be cold new snow.

Glidewax: Apply High Performance Blue Hot Wax, scrape and brush. Sprinkle on High Performance Blue Powder, iron in, let cool, scrape and brush. If you do not HP Powder, apply BP Blue Hot Wax, scrape and brush, then apply HP Blue Hot Wax, scrape and brush.

Gripwax: Roughen base with 150 grit sandpaper, iron in Nordic Base Wax Green, cork smooth, let cool. Then apply 3-4 thin layers of Nordic GripWax Blue, corking between layers.

**Structure:** A universal structure covered by one pass with the Blue Structurite tool after scraping and brushing the final Hot Wax will best suit these conditions.

Created by Ben Lustgarten, Toko Tech Team member since 2020.

Check the Wax Tips page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the How To link at TokoUS.com.

ervice