

John Craig Memorial Ski Race and Tour

McKenzie Pass, Highway 242, Sisters, OR Saturday, March 16 9 A.M. - 11 A.M. 6 or 12 Miles, Freestyle Self-timed, Out-and-back https://onc.org

Forecast/Conditions: Overnight low around 26. Saturday, sunny with a high near 50. Conditions should be firm early, with the snow softening quickly for later starters.

Glidewax: Apply High Performance Blue Hot Wax, scrape and brush. Spray on HP Liquid Paraffin Red, let stand at least 2-4 hours, then polish with the Polishing Brush Liquid Paraffin. If you do not have HP LP spray, apply BP Blue Hot Wax, scrape and brush, then apply HP Red Hot Wax, scrape and brush.

Gripwax: N/A

Structure: A universal structure covered by one pass with the Red Structurite tool after scraping and brushing the final Hot Waxor before spraying HP LP will best suit these conditions.

Created by Colin Mahood, Toko Tech Team member.

Check the Wax Tips page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the <u>How To</u> link at <u>TokoUS.com</u>.