

WAX RECOMMENDATION



FRISCO TOWN SERIES

Frisco Nordic Center, Frisco, CO – Wednesday, Jan 22

5:30 P.M., 5k, Skate, mass start

Free registration at 5 P.M. Headlamp recommended.

<https://www.townoffrisco.com/event/nordic-center-events/frisco-nordic-race-series/>

Forecast/Conditions: Overnight low zero F, temperature at start 10. Snow will be very cold, dry and still sharp from recent snowfall. The temperature drops quickly at the end of the day.

Glidewax: Apply Performance Blue Hot Wax, scrape and brush. Then apply HP Blue Hot Wax, sprinkle on X-Cold Powder, iron in together, scrape and brush

Gripwax: N/A

Structure: A fine structure covered by one pass with the Blue Structurite tool after scraping and brushing the final Hot Wax will best suit these conditions.

Created by Nelson Oldham, Toko Tech Team member since 2001

Racing-Service

Check the [Wax Tips](#) page at TokoUS.com before all of your races for the latest waxing information. Toko Race Wax Tips offer racers precise waxing advice on how to make skis perform optimally for a given event. If you do not have High Performance wax, substitute Performance or Base Performance wax of the same color (Yellow, Red or Blue), as the temperature ranges are the same. All Race Wax Tips recommend ONLY fluorine-free products. Older HP or P Toko waxes (Liquid or Hot Wax) contain fluorine. New labels look very similar but all say PFC Free. To see optimal application procedures for both Glidewax and Gripwax, go to the [How To](#) link at TokoUS.com.